257.83 (b) (2)	REPORT OF ANNUAL INSPECTION OF	CCR SU	RFAC	E IMPOUI	NDMENT	
	FACILITY NAME: Plant Yates – Ash Pond B (AP-B) OWNER/OPERATOR OF FACILITY: Georgia Power Company INSPECTION DATE: November 15, 2023					
	INSPECTING ENGINEER: Patrick B. Rhodes, PE (Georgia P.E. License # 24586)					
(i)	ANY CHANGES IN GEOMETRY OF THE IMPOUNDING			No		
	STRUCTURE SINCE THE PREVIOUS ANNUAL INSPECTION?					
	(IF YES, DESCRIBE):					
(ii)	LOCATION AND TYPE OF EXISTING INSTRUMENTA	TYPE OF EXISTING INSTRUMENTATION No Instrumentatio				
(ii)	MAXIMUM RECORDED READING OF EACH INSTRUMENT			N/A		
	SINCE PREVIOUS ANNUAL INSPECTION		N/A			
(iii)	APPROXIMATE MINIMUM, MAXIMUM AND PRESENT DEPTH AND ELEVATION OF THE					
	IMPOUNDED WATER SINCE PREVIOUS ANNUAL INSPECTION					
	MIN. DEPTH: 0 ft MAX. DEPTH: 0 ft			ENT DEPTH:		
	MIN. ELEVATION: N/A MAX. ELEVATION: N/A	١	PRESENT. ELEVATION: N/A			
(iii)	APPROXIMATE MINIMUM, MAXIMUM AND PRESENT DEPTH AND ELEVATION OF CCR					
	SINCE PREVIOUS ANNUAL INSPECTION					
	MIN. DEPTH: 0 ft. MAX. DEPTH: 0 ft.			PRESENT DEPTH: 0 ft.		
	MIN. ELEVATION: N/A MAX. ELEVATION: N/A		PRESENT ELEVATION: N/A			
(iv)	APPROXIMATE STORAGE CAPACITY OF IMPOUNDING			0 yd ³		
	STRUCTURE AT TIME OF INSPECTION				<u> </u>	
(v)	APPROXIMATE VOLUME OF IMPOUNDED WATER AND		WAT		CCR:	
	CCR AT TIME OF INSPECTION		0 yd ³	1	0 yd³	
(vi)	ANY APPEARANCE OF AN ACTUAL OR POTENTIAL					
	STRUCTURAL WEAKNESS OF THE CCR UNIT, IN ADDITION TO				M-	
	ANY EXISTING CONDITIONS THAT ARE DISRUPTING OR HAVE THE POTENTIAL TO DISRUPT THE OPERATION AND SAFETY OF				No	
	THE CCR UNIT AND APPURTENANT STRUCTURES?					
	(IF YES, DESCRIBE):					
						
(vii)	ANY OTHER CHANGE(S) WHICH MAY HAVE AFFECTED THE					
	STABILITY OR OPERATION SINCE THE PREVIOUS ANNUAL			No		
	INSPECTION?					
	(IF YES, DESCRIBE):					
	B is in the process of heigs closed by removal. CCB water and					
					on romoved T	

(1) Ash Pond B is in the process of being closed by removal. CCR, water and the impoundment dam have been removed. There was no CCR stored at the time of inspection. Portions of the original impoundment footprint are currently used for temporary stormwater storage.