257.83 (b) (2)	REPORT OF ANNUAL INSPECTION OF CCR SURFACE IMPOUNDMENT FACILITY NAME: Plant Yates Ash Pond A (AP-A) OWNER/OPERATOR OF FACILITY: Georgia Power Company						
	INSPECTION DATE: April 13, 2022						
	INSPECTING ENGINEER: Patrick B. Rhodes, P.E. (Georgia P.E. License # 24586)						
(i)	ANY CHANGES IN GEOMETRY OF THE IMPOUNDING STRUCTURE SINCE THE PREVIOUS ANNUAL INSPECTION?				į	No	
	(IF YES, DESCRIBE):						
441							
(ii)	LOCATION AND TYPE OF EXISTING INSTRUMENTATION				N/A (No Instrumentation)		
(ii)	MAXIMUM RECORDED READING OF EACH INSTRUMENT SINCE PREVIOUS ANNUAL INSPECTION N/A (No Instrumentat)						
(iii)	APPROXIMATE MINIMUM, MAXIMUM AND PRESENT DEPTH AND ELEVATION OF THE IMPOUNDED WATER SINCE PREVIOUS ANNUAL INSPECTION						
	MIN. DEPTH: 0 ft	MAX. DEPTH: 0 ft		PRESE	RESENT DEPTH: 0 ft		
	MIN. ELEVATION: N/A	MAX. ELEVATION: N/A		PRESE	RESENT. ELEVATION: N/A		
(iii)	APPROXIMATE MINIMUM, MAXIMUM AND PRESENT DEPTH AND ELEVATION OF CCR SINCE PREVIOUS ANNUAL INSPECTION.						
	MIN. DEPTH: 0 ft	MAX. DEPTH: 0 ft			PRESENT DEPTH: 0 ft		
	MIN. ELEVATION: N/A	ATION: N/A MAX. ELEVATION: N/A			PRESENT ELEVATION: N/A		
(iv) 1	APPROXIMATE STORAGE STRUCTURE AT TIME OF I		DING		O yd³		
(v)1		APPROXIMATE VOLUME OF IMPOUNDED WATER AND CCR AT TIME OF INSPECTION			ATER: /d³	CCR: 0 yd ³	
(vi)	ANY APPEARANCE OF AN ACTUAL OR POTENTIAL STRUCTURAL WEAKNESS OF THE CCR UNIT, IN ADDITION TO ANY EXISTING CONDITIONS THAT ARE DISRUPTING OR HAVE THE POTENTIAL TO DISRUPT THE OPERATION AND SAFETY OF THE CCR UNIT AND APPURTENANT STRUCTURES? (IF YES, DESCRIBE):					-	
(vii)	ANY OTHER CHANGE(S) WHICH MAY HAVE AFFECTED THE STABILITY OR OPERATION SINCE THE PREVIOUS ANNUAL INSPECTION? (IF YES, DESCRIBE):					No	

^{*} The ash has been removed as a part of the closure by removal process and the former pond no longer has the ability to impound water.