257.83 (b) (2)	REPORT OF ANNUAL INSPECTION OF CCR SURFACE IMPOUNDMENT FACILITY NAME: Plant Yates Ash Pond A (AP-A)						
	OWNER/OPERATOR OF FACILITY: Georgia Power Company						
	INSPECTION DATE: March 17, 2021						
	INSPECTING ENGINEER: Patrick B. Rhodes, P.E. (Georgia P.E. License # 24586)						
(i)	ANY CHANGES IN GEOMETRY OF THE IMPOUNDING STRUCTURE SINCE THE PREVIOUS ANNUAL INSPECTION?				No		
	(IF YES, DESCRIBE):						
(ii)	LOCATION AND TYPE OF EXISTING INSTRUMENTATION N/A (No Instrumentation						
(ii)	MAXIMUM RECORDED RE SINCE PREVIOUS ANNUAL	ADING OF EACH INSTRUM	ENT				
(iii)	APPROXIMATE MINIMUM, MAXIMUM AND PRESENT DEPTH AND ELEVATION OF THE IMPOUNDED WATER SINCE PREVIOUS ANNUAL INSPECTION						
	MIN. DEPTH: 0 ft	MAX. DEPTH: 0 ft	Service Services	ESENT DEPTH: 0 ft			
		MAX. ELEVATION: N/A					
(iii)	APPROXIMATE MINIMUM, MAXIMUM AND PRESENT DEPTH AND ELEVATION OF CCR SINCE PREVIOUS ANNUAL INSPECTION.						
	MIN. DEPTH: 0 ft.	DEPTH: 0 ft. MAX. DEPTH: 0 ft.			PRESENT DEPTH: 0 ft.		
	MIN. ELEVATION: N/A MAX. ELEVATION: N/A			PRESENT ELEVATION: N/A			
(iv) 1	APPROXIMATE STORAGE STRUCTURE AT TIME OF I	CAPACITY OF IMPOUNDING NSPECTION.	G	0 yd³			
(v)1	APPROXIMATE VOLUME OF IMPOUNDED WATER AND CCR AT TIME OF INSPECTION		- 1	WAT 0 yd		CCR: 0 yd ³	
(vi)	ANY APPEARANCE OF AN ACTUAL OR POTENTIAL STRUCTURAL WEAKNESS OF THE CCR UNIT, IN ADDITION TO ANY EXISTING CONDITIONS THAT ARE DISRUPTING OR HAVE THE POTENTIAL TO DISRUPT THE OPERATION AND SAFETY OF THE CCR UNIT AND APPURTENANT STRUCTURES? (IF YES, DESCRIBE):						
(vii)	ANY OTHER CHANGE(S) WHICH MAY HAVE AFFECTED THE STABILITY OR OPERATION SINCE THE PREVIOUS ANNUAL INSPECTION? (IF YES, DESCRIBE):				No		

^{*} The ash has been removed as a part of the closure by removal process and the former pond no longer has the ability to impound water.

No. 24586 PROFESSIONAL