257.83 (b) (2)	REPORT OF ANNUAL INSPECTION OF CCR SURFACE IMPOUNDMENT					
(-/(-/	FACILITY NAME: Plant McDonough AP2					
	OWNER/OPERATOR OF FACILITY: Georgia Power Company					
	INSPECTION DATE: March 20, 2019					
	INSPECTING ENGINEER: Patrick B. Rhodes, P.E. (Georgia P.E. License # 24586)					
	Southern Company Services Fossil Dam Safety					
	Based on the results of the inspection and review of the data provided by a qualified Professional Engineer, it is my professional opinion that the report has been completed in accordance with 40 CFR 257.83(b).					
(i)	ANY CHANGES IN GEOMETRY OF THE IMPOUNDING STRUCTURE				No	
	SINCE THE PREVIOUS ANNUAL INSPECTION (YES OR NO)?					
	(IF YES, DESCRIBE): N/A					
(ii)	LOCATION AND TYPE OF E	F EXISTING INSTRUMENTATION			N/A (no instrumentation)	
(ii)	MAXIMUM RECORDED READING OF EACH INSTRUMENT SINCE PREVIOUS ANNUAL INSPECTION				N/A (no instrumentation)	
(iii)	APPROXIMATE MINIMUM, MAXIMUM AND PRESENT DEPTH AND ELEVATION OF THE IMPOUNDED					
	WATER SINCE PREVIOUS ANNUAL INSPECTION					
	MIN. DEPTH: 0 ft* MAX. DEPTH: 0 ft*			PRESENT DEPTH: 0 ft*		
/···\	MIN. ELEVATION: N/A * MAX. ELEVATION: N/A *			PRESENT ELEVATION: N/A *		
(iii)	APPROXIMATE MINIMUM, MAXIMUM AND PRESENT DEPTH AND ELEVATION OF CCR SINCE PREVIOUS ANNUAL INSPECTION.					
	· · · · · · · · · · · · · · · · · · ·			PRESE	RESENT DEPTH: 0 ft*	
		IN. ELEVATION: N/A * MAX. ELEVATION: N/A *		PRESENT ELEVATION: N/A		
(iv)					CDonough no longer burns	
(,	IMPOUNDING STRUCTURE	coal, thus no longer generates nor disposes				
				_	f CCR in this area.*	
(v)	APPROXIMATE VOLUME OF IMPOUNDED WATER AND CCR AT TIME OF INSPECTION		WATER: 0 cu	yds *	CCR: 0 cu yds *	
(vi)	ANY APPEARANCE OF AN ACTUAL OR POTENTIAL STRUCTURAL WEAKNESS OF THE CCR UNIT, IN ADDITION TO ANY EXISTING					
	CONDITIONS THAT ARE DISRUPTING OR HAVE THE POTENTIAL TO				No	
	DISRUPT THE OPERATION AND SAFETY OF THE CCR UNIT AND					
	APPURTENANT STRUCTURES (YES OR NO)?					
	(IF YES, DESCRIBE): N/A					
(vii)	ANY OTHER CHANGE(S) WHICH MAY HAVE AFFECTED THE STABILITY OR OPERATION SINCE THE PREVIOUS ANNUAL INSPECTION (YES OR NO)?				No	
	(IF YES, DESCRIBE): N/A					
	1	- 				

^{*} The ash pond has been dewatered, no longer has the ability to impound water and ash has been removed as a part of the closure by removal process.