

|                  |   |                          |
|------------------|---|--------------------------|
| 257.84<br>(b)(2) | <b>2019 REPORT OF ANNUAL INSPECTION OF CCR LANDFILL</b>   |                          |
|                  | <b>CCR LANDFILL NAME:</b> Plant Wansley Private Industrial Solid Waste (Coal Combustion By-Product) Disposal Facility (Active Cell 1, and Cells 2, & 3). Permit # 074-005D(LI). |                          |
|                  | <b>OWNER OF CCR LANDFILL:</b> Georgia Power Company   |                          |
|                  | <b>INSPECTION DATE:</b> 11/25/2019  |                          |
|                  | <b>INSPECTING ENGINEER:</b> Gary H. McWhorter, P.E. GA Reg. #PE012687   |                          |
| (i)              | <b>ANY CHANGES IN GEOMETRY OF THE STRUCTURE SINCE THE PREVIOUS ANNUAL INSPECTION?</b>   | <b>NO <sup>(1)</sup></b> |
|                  | (IF YES, DESCRIBE):   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |
|                  |   |                          |

(1) The geometry of the structure (permitted footprint and final grades) has not changed since the last inspection, with the exception of the additional placement or marketing of CCR.  
(2) Survey dated 11/18/2019, CCR volume: Cell 1 – 514,593 cy; Cell 2 – 870 cy; cell 3 – 61,830 cy.

