

257.83	REPORT OF ANNU	JAL INSPECTION OF CCR	SURF	AC	E IMPOU	NDMENT	
(b) (2)							
	FACILITY NAME: Plant Hammond, Ash Pond 1 (AP-1) OWNER/OPERATOR OF FACILITY: Georgia Power Company INSPECTION DATE: October 19, 2021						
	INSPECTING ENGINEER: Jacob A. Jordan, P.E. (GA PE # PE028586)						
(i)	ANY CHANGES IN GEOMETRY OF THE IMPOUNDING STRUCTURE SINCE THE PREVIOUS ANNUAL INSPECTION?				NO		
	(IF YES, DESCRIBE):						
(ii)	LOCATION AND TYPE OF EXISTING INSTRUMENTATION				SEE ATTACHED PLAN		
(ii)	MAXIMUM RECORDED READING OF EACH INSTRUMENT SINCE PREVIOUS ANNUAL INSPECTION				SEE ATTACHED TABLE		
(iii)	APPROXIMATE MINIMUM, MAXIMUM AND PRESENT DEPTH AND ELEVATION OF THE						
	IMPOUNDED WATER SINCE PREVIOUS ANNUAL INSPECTION						
	MIN. DEPTH: 0 ft	MAX. DEPTH: 18 ft	PRES	ENT	DEPTH: 4.5		
	MIN. ELEVATION: 574.8	MAX. ELEVATION: 580.9	PRESI	RESENT. ELEVATION: 576.5			
(iii)	APPROXIMATE MINIMUM, MAXIMUM AND PRESENT DEPTH AND ELEVATION OF CCR SINCE PREVIOUS ANNUAL INSPECTION.						
	MIN. DEPTH: 0 ft	MAX. DEPTH: 19 ft	PRES	SENT	T DEPTH: up to 19 ft		
	MIN. ELEVATION: 565	MAX. ELEVATION: 584		RESENT ELEVATION: up to 584			
(iv)	APPROXIMATE STORAGE CAPACITY OF IMPOUNDING STRUCTURE AT TIME OF INSPECTION. 833,785 cy (1)					35 cy ⁽¹⁾	
(v)	APPROXIMATE VOLUME OF IMPOUNDED WATER AND CCR AT TIME OF INSPECTION			ATE	R: 00 cy ⁽¹⁾	CCR: 530,000 cy ⁽¹⁾	
(vi)	ANY APPEARANCE OF AN ACTUAL OR POTENTIAL STRUCTURAL WEAKNESS OF THE CCR UNIT, IN ADDITION TO ANY EXISTING CONDITIONS THAT ARE DISRUPTING OR HAVE THE POTENTIAL TO DISRUPT THE OPERATION AND SAFETY OF THE CCR UNIT AND APPURTENANT STRUCTURES?						
	(IF YES, DESCRIBE):						
(vii)	ANY OTHER CHANGE(S) WHICH MAY HAVE AFFECTED THE STABILITY OR OPERATION SINCE THE PREVIOUS ANNUAL INSPECTION?				NO		
	(IF YES, DESCRIBE):						

(1) Cubic yard estimates are derived by qualified personnel from available information.





INSTRUMENTATION PLAN
PLANT HAMMOND ASH POND 1

INSTRUMENTATION READINGS PLANT HAMMOND ASH POND 1

PIEZOMETER NUMBER	MAXIMUM RECORDED READING*		
AP1-1	EL 573		
AP1-2	EL 576		
AP1-3	EL 578		

^{*}MAXIMUM RECORDED READING SINCE LAST ANNUAL INSPECTION; ROUNDED TO NEAREST FOOT

