

<b>257.84 (b)(2)</b>	<b>2019 REPORT OF ANNUAL INSPECTION OF CCR LANDFILL</b>	
	<b>CCR LANDFILL NAME:</b> Plant Hammond – Huffaker Road Private Industrial Solid Waste (Coal Combustion By-Product) Disposal Facility (Active Cells A & B, E). Permit # 057-022D(LI).	
	<b>OWNER OF CCR LANDFILL:</b> Georgia Power Company	
	<b>INSPECTION DATE:</b> 11/19/2019	
	<b>INSPECTING ENGINEER:</b> Gary H. McWhorter, P.E. GA Reg. #PE012687	
<b>(i)</b>	<b>ANY CHANGES IN GEOMETRY OF THE STRUCTURE SINCE THE PREVIOUS ANNUAL INSPECTION?</b>	<b>NO <sup>(1)</sup></b>
	<b>(IF YES, DESCRIBE):</b>	
<b>(ii)</b>	<b>APPROXIMATE VOLUME OF CCR CONTAINED IN THE UNIT AT THE TIME OF INSPECTION?</b>	<b>1,026,395 cy <sup>(2)</sup></b>
<b>(iii)</b>	<b>ANY APPEARANCE OF AN ACTUAL OR POTENTIAL STRUCTURAL WEAKNESS OF THE CCR UNIT, IN ADDITION TO ANY EXISTING CONDITIONS THAT ARE DISRUPTING OR HAVE THE POTENTIAL TO DISRUPT THE OPERATION AND SAFETY OF THE CCR UNIT?</b>	<b>NO</b>
	<b>(IF YES, DESCRIBE):</b>	
<b>(iv)</b>	<b>ANY OTHER CHANGE(S) WHICH MAY HAVE AFFECTED THE STABILITY OR OPERATION OF THE CCR UNIT SINCE THE PREVIOUS ANNUAL INSPECTION?</b>	<b>NO</b>
	<b>(IF YES, DESCRIBE):</b>	

- (1) The geometry of the structure (permitted footprint and final grades) has not changed since the last inspection, with the exception of the additional placement of CCR.
- (2) CCR volume (corrected by survey dated 11/5/2019): Cells A & B (operated as one cell) – 287,982 cy; Cell E – 738,413 cy (previous volume estimate did not include CCR and soil liner removed from Cell A in 2013 prior to retrofit and placed in Cell E.)

Gary H. McWhorter, P.E.  
 GA. Reg. #PE012687  
 11/19/20