257.83 (b) (2)	REPORT OF ANNUAL INSPECTION OF CCR SURFACE IMPOUNDMENT			
	FACILITY NAME: Plant McDonough AP4			
	OWNER/OPERATOR OF FACILITY: Georgia Power Company			
	INSPECTION DATE: March 22, 2017			
	INSPECTING ENGINEER: Patrick B. Rhodes, P.E. (Georgia P.E. License # 24586) Southern Company Services Fossil Dam Safety			
	Based on the results of the inspection and review of the data provided by a qualified Professional Engineer, it is my professional opinion that the report has been completed in accordance with 40 CFR 257.83(b).			
(i)	**ANY CHANGES IN GEOMETRY OF THE IMPOUNDING STRUCTURE SINCE THE PREVIOUS ANNUAL INSPECTION (YES OR NO)?**			**N/A ***
	(IF YES, DESCRIBE): N/A			
(ii)	**LOCATION AND TYPE OF EXISTING INSTRUMENTATION**			**See attached figure**
(ii)	**MAXIMUM RECORDED READING OF EACH INSTRUMENT SINCE PREVIOUS ANNUAL INSPECTION**			**N/A***
(iii)	**APPROXIMATE MINIMUM, MAXIMUM AND PRESENT DEPTH AND ELEVATION OF THE IMPOUNDED WATER SINCE PREVIOUS ANNUAL INSPECTION**			
	MIN. DEPTH: N/A *	MAX. DEPTH: N/A *	PRESENT DEPTH: 0**	
	MIN. ELEVATION: N/A *	MAX. ELEVATION: N/A *	PRESENT ELEVATION: N/A	
(iii)	**APPROXIMATE MINIMUM, MAXIMUM AND PRESENT DEPTH AND ELEVATION OF CCR SINCE PREVIOUS ANNUAL INSPECTION.**			
	MIN. DEPTH: N/A *	MAX. DEPTH: N/A *	PRESENT DEPTH: Up to 120 ft	
	MIN. ELEVATION: N/A *	MAX. ELEVATION: N/A *	PRESENT ELEVATION: Up to EL 850 ft	
(iv)	**APPROXIMATE STORAGE CAPACITY OF IMPOUNDING STRUCTURE AT TIME OF INSPECTION.**	N/A – Plant McDonough no longer burns coal, thus no longer generates nor disposes of CCR in this area.		
(v)	**APPROXIMATE VOLUME OF IMPOUNDED WATER AND CCR AT TIME OF INSPECTION**	**WATER:** 0 cu yds **	**CCR:** 2,000,000 cu yds ***	
(vi)	**ANY APPEARANCE OF AN ACTUAL OR POTENTIAL STRUCTURAL WEAKNESS OF THE CCR UNIT, IN ADDITION TO ANY EXISTING CONDITIONS THAT ARE DISRUPTING OR HAVE THE POTENTIAL TO DISRUPT THE OPERATION AND SAFETY OF THE CCR UNIT AND APPURTENANT STRUCTURES (YES OR NO)?**			**NO**
	(IF YES, DESCRIBE): N/A			
(vii)	**ANY OTHER CHANGE(S) WHICH MAY HAVE AFFECTED THE STABILITY OR OPERATION SINCE THE PREVIOUS ANNUAL INSPECTION (YES OR NO)?**			**N/A ***
	(IF YES, DESCRIBE): N/A			

* This is the first 'annual inspection by a qualified professional engineer' performed in accordance with 40 CFR Part 257.83. This information will be included in subsequent annual inspection reports.

** The ash pond is in the process of closure construction and has been dewatered.

*** Cubic yard estimates are derived by qualified personnel from available information.

GEORGIA REGISTERED No. 17419 PROFESSIONAL ENGINEER JAMES C. PEGUES, JR.

INSTRUMENTATION LOCATION
PLANT MCDONOUGH AP4