

<b>257.84 (b)(2)</b>	<b>2025 REPORT OF ANNUAL INSPECTION OF CCR LANDFILL</b>	
	<b>CCR LANDFILL NAME:</b> Plant Wansley CCR Landfill (Active Cells 1, 2, & 3). Permit 074-005D(CCR)	
	<b>OWNER OF CCR LANDFILL:</b> Georgia Power Company	
	<b>INSPECTION DATE:</b> October 28, 2025	
	<b>INSPECTING ENGINEER:</b> Gary H. McWhorter, P.E. GA Reg. #PE012687	
<b>(i)</b>	<b>ANY CHANGES IN GEOMETRY OF THE STRUCTURE SINCE THE PREVIOUS ANNUAL INSPECTION?</b>	<b>NO <sup>(1)</sup></b>
	(IF YES, DESCRIBE):	
<b>(ii)</b>	<b>APPROXIMATE VOLUME OF CCR CONTAINED IN THE UNIT AT THE TIME OF INSPECTION?</b>	<b>165,635yd<sup>3</sup> <sup>(2)</sup></b>
<b>(iii)</b>	<b>ANY APPEARANCE OF AN ACTUAL OR POTENTIAL STRUCTURAL WEAKNESS OF THE CCR UNIT, IN ADDITION TO ANY EXISTING CONDITIONS THAT ARE DISRUPTING OR HAVE THE POTENTIAL TO DISRUPT THE OPERATION AND SAFETY OF THE CCR UNIT?</b>	<b>NO</b>
	(IF YES, DESCRIBE):	
<b>(iv)</b>	<b>ANY OTHER CHANGE(S) WHICH MAY HAVE AFFECTED THE STABILITY OR OPERATION OF THE CCR UNIT SINCE THE PREVIOUS ANNUAL INSPECTION?</b>	<b>NO</b>
	(IF YES, DESCRIBE):	

(1) The geometry of the structure (permitted footprint) has not changed since the last inspection. As of May 5, 2025, all CCR has been removed for market from Cell 1 & Cell 2 for liner modification construction activities.

(2) Approximate CCR volume (by survey dated 11/14/2024): Cell 3 – 165,635 yd<sup>3</sup>.

